



CITY OF BEND

MURPHY CORRIDOR IMPROVEMENTS PROJECT

Country Club Drive Roundabout Construction Detours

September 8 – November 2020 (weather dependent)



Late August 2020

Construction of a temporary two-way bypass road to accommodate traffic around the Country Club Dr. Roundabout construction area. The bypass road will connect traffic on Country Club Dr. to eastbound traffic on Murphy Rd.


September 8 – November 2020

Full closure at the intersection of Murphy Rd. and Country Club Dr. during construction of the Country Club Dr. roundabout. During the intersection closure, a temporary two-way bypass road will connect Country Club Dr. (south) to Murphy Rd. (east). The bypass road will provide a temporary roadway connection toward the area of Jewell Elementary School and south toward the Bend Fire Station.



Safety Connectivity Mobility

Sign up for weekly construction updates at bendoregon.gov/MurphyProject



DETOURS

September 8 – November 2020

WESTBOUND DETOUR

Take the Murphy Rd. bypass road to Country Club Dr. Turn right on Knott Rd. Turn right on China Hat Rd. Turn right on Parrell Rd.

EASTBOUND DETOUR

Take Murphy Rd. to Parrell Rd. Continue on Parrell Rd. and turn right on Brosterhous Rd. and follow to stop sign. Turn right on Brosterhous Rd. and follow through Brosterhous Roundabout to Murphy Rd.

Local access to residences and emergency traffic will be maintained at all times.

LEGEND

- Road Closure
- Westbound Detour
- Eastbound Detour
- Future Murphy Road
- Temporary Bypass
- Roundabout



Accommodation Information For People With Disabilities. To obtain this information in an alternate format such as Braille, large print or electronic formats, please contact MurphyProjectTeam@bendoregon.gov or 541-322-9919. Relay Users Dial 7-1-1.