


LEGEND:

PAVEMENT MAINTENANCE TAXIWAY SAFETY AREA

TAXIWAY OBJECT FREE AREA TAXILANE OBJECT FREE AREA NORTHWEST TAXILANE MAINTENANCE (WORK AREA #1) SCALE: 1" = 40'




NOTES:

- 1. FOR PRIVATE HANGARS: BY RULE, THE 50 FEET OF PAVEMENT AREA IN FRONT OF A PRIVATELY-OWNED HANGAR IS CONSIDERED INELIGIBLE FOR FEDERAL FUNDING BY THE FAA. HOWEVER, IF PAVEMENT WITHIN THIS 50-FOOT AREA IS IN THE PUBLIC RIGHT OF WAY (IN THIS CASE, AN ADG-I TAXILANE) THAT PUBLIC PAVEMENT IS ELIGIBLE FOR FEDERAL FUNDING. THE PAVEMENT BETWEEN THE ADG-I TAXILANE EDGE AND THE PRIVATE HANGAR FACE REMAINS INELIGIBLE FOR FEDERAL FUNDING. (TYP ALL.)
- 2. FOR PUBLICALLY-OWNED HANGARS, THE PAVEMENT BETWEEN THE ADG-I TAXILANE EDGE AND THE HANGAR FACE IS CONSIDERED ELIGIBLE FOR FEDERAL FUNDING BY THE FAA. (TYP ALL.)

30% PLANS - NOT FOR CONSTRUCTION A.IP. NO. 3-41-0037-037-2024

_____ TLOFA _____



95265PEN OR LAND OR LA RENEWS: 06/30/25

VERIFY SCALES BAR IS ONE INCH ON ORIGINAL DRAWING. IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

	REVISIONS	APPR	BY	DATE	NO.
CEN					
CEN WES					
ENGINEE					
DATE:					
SEPTEMBER 20					

1020 SW EMKAY DRIVE, #100 DRAWN BY: BEND, OR 97702 GINEERING 541.382.2423 FAX PROJECT NO: SCALE:

10051.133.01

DESIGNED BY: TJS CHECKED BY: TH3

AS NOTED

CITY OF BEND BEND MUNICIPAL AIRPORT TAXILANE MAINTENANCE

NORTHWEST TAXILANE MAINTENANCE AREA

DRAWING NO. G-05 SHEET NO.


5 OF 25

(WORK AREA #1)

IN COLOR. THE FOLLOWING COLORS SHOULD BE DISTINGUISHABLE WHEN PRINTED CORRECTLY:

BLUE

THIS PLAN SHEET IS INTENDED TO BE VIEWED



LEGEND:


TAXILANE OBJECT FREE AREA

PAVEMENT MAINTENANCE TAXIWAY SAFETY AREA TAXIWAY OBJECT FREE AREA

_____ TLOFA _____

MIDWEST TAXILANE MAINTENANCE (WORK AREA #2) SCALE: 1" = 40'

G-06



NOTES:

- 1. FOR PRIVATE HANGARS: BY RULE, THE 50 FEET OF PAVEMENT AREA IN FRONT OF A PRIVATELY-OWNED HANGAR IS CONSIDERED INELIGIBLE FOR FEDERAL FUNDING BY THE FAA. HOWEVER, IF PAVEMENT WITHIN THIS 50-FOOT AREA IS IN THE PUBLIC RIGHT OF WAY (IN THIS CASE, AN ADG-I TAXILANE) THAT PUBLIC PAVEMENT IS ELIGIBLE FOR FEDERAL FUNDING. THE PAVEMENT BETWEEN THE ADG-I TAXILANE EDGE AND THE PRIVATE HANGAR FACE REMAINS INELIGIBLE FOR FEDERAL FUNDING. (TYP ALL.)
- 2. FOR PUBLICALLY-OWNED HANGARS, THE PAVEMENT BETWEEN THE ADG-I TAXILANE EDGE AND THE HANGAR FACE IS CONSIDERED ELIGIBLE FOR FEDERAL FUNDING BY THE FAA. (TYP ALL.)

AS NOTED

30% PLANS - NOT FOR CONSTRUCTION A.IP. NO. 3-41-0037-037-2024



OR THE TO A. HAGEDOR RENEWS: 06/30/25

VERIFY SCALES BAR IS ONE INCH ON ORIGINAL DRAWING. IF NOT ONE INCH ON THIS SHEET, ADJUST SCALES ACCORDINGLY.

NO.	DATE	BY	APPR	REVISIONS		
						ı
						Ì
						- E
					F	DA

CENTURY	BEND OFFICE	DESIGNED BY:		
WEST	1020 SW EMKAY DRIVE, #100 BEND, OR 97702 - 541.322.8962	DRAWN BY: TJS		
NGINEERING	541.382.2423 FAX	CHECKED BY: TH3		
:	PROJECT NO:	SCALE:		
SEPTEMBER 2024	10051.133.01	AS NOTE		

CITY OF BEND BEND MUNICIPAL AIRPORT TAXILANE MAINTENANCE

MIDWEST TAXILANE MAINTENANCE AREA (WORK AREA #2)

G-06 SHEET NO.

6 OF 25

BLUE

THIS PLAN SHEET IS INTENDED TO BE VIEWED IN COLOR. THE FOLLOWING COLORS SHOULD

BE DISTINGUISHABLE WHEN PRINTED

CORRECTLY:

